

SAFETY ALERT



This is an actual or reenactment photo.

Date of incident: XXXXX

Time of incident: XXXXX

Location: R/M plant

Category of incident:

(place an X on all that apply)

- Fatality
- Injury
- Driving-related accident
- Near miss
- Other

Description:

Employee was washing down his truck when he stepped down off of the ICC (DOT) bumper on rear of truck and slipped and fell injuring ribs and lower back.

Recommendations:

1. ICC (DOT) bumpers are not designed to be used for steps and all drivers should be reminded of this; please use this alert for your next safety meeting and document attendance.
2. Each plant either has a wash rack or access ladders for proper wash down; drivers must use the proper method available.
3. Proper wash down methods should be covered in the daily safety task assessment.